

EXPANDED FUNGAL REPORT TM

Prepared Exclusively For

<Client Name>


<Street Address> <City,
State, Zip>

<Phone:000-000-0000>

Report Date: 00/00/0000
Project: <Street Address>
EMSL Order: 000000000

AIHA LAP, LLC.

EMLAP #000000



This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

1. Description of Analysis

Analytical Laboratory

EMSL Analytical, Inc. (EMSL) is a nationwide, full service, analytical testing laboratory network providing Asbestos, Mold, Indoor Air Quality, Microbiological, Environmental, Chemical, Forensic, Materials, Industrial Hygiene and Mechanical Testing services since 1981. Ranked as the premier independently owned environmental testing laboratory in the nation, EMSL puts analytical quality as its top priority. This quality is recognized by many well-respected federal, state and private accrediting agencies, and assured by our high quality personnel, including many Ph.D. microbiologists and mycologists.

EMSL is an independent laboratory that performed the analysis of these samples. EMSL did not conduct the sampling or site investigation for this report. The samples referenced herein were analyzed under strict quality control procedures using state-of-the-art microbiological methods. The analytical methods used and the data presented are scientifically and legally defensible.

The laboratory data is provided in compliance with ISO-IEC 17025 guidelines for the particular test(s) requested, including any associated limitations for the methods employed. These data are intended for use by professionals having knowledge of the testing methods necessary to interpret them accurately.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310

Fax: (206) 900-8789

Web: <http://www.emsl.com>

Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Air Samples - Spore traps:

Spore traps are commercially available sampling devices that capture airborne particles on an adhesive slide. Air is pulled through the device using a vacuum pump. Spores, as well as other airborne particles, are impacted on the collection adhesive. Using spore trap collection methods has inherent limitations. These collection methods are biased towards larger spore sizes.

The analysis for total spore counts is a direct microscopic examination and does not include culturing or growing the fungi. Therefore, the results include both viable and non-viable spores. Some fungal groups produce similar spore types that cannot be distinguished by direct microscopic examination alone (i.e., *Aspergillus/Penicillium*, and others). Other spore types may lack distinguishing features that aid in their identification. These types are grouped into larger categories such as Ascospores or Basidiospores.

Fungal spores are identified and grouped by morphological characteristics including color, shape, septation, ornamentation, and fruiting structures (if present) which are compared to published mycological identification keys and texts. EMSL reports provide spore counts per cubic meter of air to three significant figures. Please note that each spore category is reported to three significant figures. Due to rounding and the application of three significant figures the sum of the individual spore numbers may not equal the total spore count on the report. EMSL does not maintain responsibility for final volume concentrations (counts/m³) since this volume is provided by the field collector and can not be verified by EMSL.

EMSL analyzes spore traps using phase contrast microscopy. There is a wide choice of collection devices (Air-O-Cell, Micro-5, Burkhard, etc.) on the market. Differences in analytical method may exist between spore trap devices.

Spore trap results are reported in spores per cubic meter of air. Due to the other airborne particles collected with the spores, EMSL reports a background particle density. Background density is an indication of overall particulate matter present on the sample (i.e. dust in the air). High background concentrations may obscure spores such as the *Penicillium/Aspergillus* group. The rating system is from 1-5 with 1 = 1 - 25% of the background obscured by material, 2 = 26 - 50%, 3 = 51 - 75%, 4 = 76% - 99%, 5 = 100% or overloaded. A background rating of 4 or higher should be regarded as a minimum count since the actual concentrations may be higher than those reported. EMSL will not be held responsible for overloading of samples. Sample volumes are left to the discretion of the company or persons conducting the fieldwork.

Skin fragment density is the percentage of skin cells making up the total background material, 1 = 1 - 25%, 2 = 26 - 50%, 3 = 51 - 75%, 4 = 76-100%. Skin fragment density is considered an indication of the general cleanliness in the area sampled. It has been estimated that up to 90% of household dust consists of dead skin cells.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

2. Analytical Results

See attached data reports and charts.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Spore Trap ASSESSMENT Report™ Air-O-Cell™ Analysis of Fungal Spores & Particulates (Methods MICRO-SOP-201, ASTM D7391)

	Particle Identification	Raw Count	(Count/m³)	% of Total	Interpretation Guideline
00000000-0001	Alternaria (Ulocladium)	-	-	-	
	Ascospores	100	2180	14.5	
Client Sample ID	Aspergillus/Penicillium	10	220	1.5	
#1	Basidiospores	579	12600	83.9	
	Bipolaris++	-	-	-	
	Chaetomium++	-	-	-	
Location	Cladosporium	-	-	-	
Outside control	Curvularia	-	-	-	
	Epicoccum	-	-	-	
Sample Volume (L)	Fusarium++	-	-	-	
150	Ganoderma	1	20	0.1	
	Myxomycetes++	-	-	-	
	Pithomyces++	-	-	-	
Sample Type	Rust	-	-	-	
Background	Scopulariopsis/Microascus	-	-	-	
	Stachybotrys/Memnoniella	-	-	-	
Comments	Unidentifiable Spores	-	-	-	
	Zygomycetes	-	-	-	
	Total Fungi	690	15020	100	
	Hyphal Fragment	-	-	-	
	Insect Fragment	-	-	-	
	Pollen	-	-	-	
Analytical Sensitivity 600x: 22 counts/cubic meter		Skin Fragments:		1 to 4 (low to high)	
Analytical Sensitivity 300x *: 7* counts/cubic meter		Fibrous Particulate: 1		1 to 4 (low to high)	
		Background: 1		1 to 4 (low to high); 5 (overloaded)	

- Not commonly found growing indoors, spores likely come from outside.
- Spores reported to be able to cause allergies in individuals.
- Potential for mycotoxin production exists with these fungi.
- These fungi are considered water damage indicators.

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category

Rudy Baum, Interim Laboratory Manager
or Other Approved Signatory

Initial report from: 11/02/2021 09:01:31

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. Seattle, WA AIHA-LAP, LLC-EMLAP Accredited #167337

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Spore Trap ASSESSMENT Report™ Air-O-Cell(™) Analysis of Fungal Spores & Particulates (Methods MICRO-SOP-201, ASTM D7391)

	Particle Identification	Raw Count	(Count/m ³)	% of Total	Interpretation Guideline
00000000-0002	Alternaria (Ulocladium)	-	-	-	
	Ascospores	38	830	15.7	Acceptable
Client Sample ID #2	Aspergillus/Penicillium	-	-	-	
	Basidiospores	202	4410	83.2	Acceptable
	Bipolaris++	-	-	-	
Location Family room	Chaetomium++	-	-	-	
	Cladosporium	-	-	-	
	Curvularia	-	-	-	
Sample Volume (L) 150	Epicoccum	-	-	-	
	Fusarium++	-	-	-	
	Ganoderma	1	20	0.4	Acceptable
Sample Type Inside	Myxomycetes++	2	40	0.8	Slightly Elevated
	Pithomyces++	-	-	-	
	Rust	-	-	-	
Comments	Scopulariopsis/Microascus	-	-	-	
	Stachybotrys/Memnoniella	-	-	-	
	Unidentifiable Spores	-	-	-	
	Zygomycetes	-	-	-	
	Total Fungi	243	5300	100	Acceptable
	Hyphal Fragment	-	-	-	
	Insect Fragment	-	-	-	
	Pollen	-	-	-	
Analytical Sensitivity 600x: 22 counts/cubic meter		Skin Fragments: 1		1 to 4 (low to high)	
Analytical Sensitivity 300x *: 7* counts/cubic meter		Fibrous Particulate: 1		1 to 4 (low to high)	
		Background: 1		1 to 4 (low to high); 5 (overloaded)	

- Acceptable** Concentration at or below background
- Slightly Elevated** Concentration above background
- ELEVATED** Concentration 10X or more above background

- Not commonly found growing indoors, spores likely come from outside.
- Spores reported to be able to cause allergies in individuals.
- Potential for mycotoxin production exists with these fungi.
- These fungi are considered water damage indicators.

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category

Initial report from: 11/02/2021 09:01:31

Rudy Baum, Interim Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.
Samples analyzed by EMSL Analytical, Inc. Seattle, WA AIHA-LAP, LLC-EMLAP Accredited #167337

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Spore Trap ASSESSMENT Report™ Air-O-Cell™ Analysis of Fungal Spores & Particulates (Methods MICRO-SOP-201, ASTM D7391)

	Particle Identification	Raw Count	(Count/m³)	% of Total	Interpretation Guideline
00000000-0003	Alternaria (Ulocladium)	-	-	-	
	Ascospores	19	420	11.8	Acceptable
Client Sample ID #3	Aspergillus/Penicillium	-	-	-	
	Basidiospores	123	2680	75.5	Acceptable
	Bipolaris++	-	-	-	
	Chaetomium++	-	-	-	
Location Bedroom	Cladosporium	18	390	11	ELEVATED
	Curvularia	-	-	-	
Sample Volume (L) 150	Epicoccum	1	20	0.6	Slightly Elevated
	Fusarium++	-	-	-	
Sample Type Inside	Ganoderma	-	-	-	
	Myxomycetes++	2	40	1.1	Slightly Elevated
Comments	Pithomyces++	-	-	-	
	Rust	-	-	-	
	Scopulariopsis/Microascus	-	-	-	
	Stachybotrys/Memnoniella	-	-	-	
	Unidentifiable Spores	-	-	-	
	Zygomycetes	-	-	-	
	Total Fungi	163	3550	100	Acceptable
	Hyphal Fragment	-	-	-	
	Insect Fragment	-	-	-	
	Pollen	-	-	-	
Analytical Sensitivity 600x: 22 counts/cubic meter		Skin Fragments: 2		1 to 4 (low to high)	
Analytical Sensitivity 300x *: 7* counts/cubic meter		Fibrous Particulate: 1		1 to 4 (low to high)	
		Background: 3		1 to 4 (low to high); 5 (overloaded)	

- Acceptable** Concentration at or below background
- Slightly Elevated** Concentration above background
- ELEVATED** Concentration 10X or more above background

- Not commonly found growing indoors, spores likely come from outside.
- Spores reported to be able to cause allergies in individuals.
- Potential for mycotoxin production exists with these fungi.
- These fungi are considered water damage indicators.

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category

Initial report from: 11/02/2021 09:01:31

Rudy Baum, Interim Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.
Samples analyzed by EMSL Analytical, Inc. Seattle, WA AIHA-LAP, LLC-EMLAP Accredited #167337

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.


5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Spore Trap Report: Total Counts



Ascospores	Aspergillus/Penicillium	Basidiospores	Cladosporium
Epicoccum	Ganoderma	Myxomycetes++	

* The chart is displayed using a logarithmic scale. Bar size is not directly proportional to the number of spores.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.


5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Spore Trap Report: Total Counts



Ascospores	Aspergillus/Penicillium	Basidiospores	Cladosporium
Epicoccum	Ganoderma	Myxomycetes++	

* The chart is displayed using a logarithmic scale. Bar size is not directly proportional to the number of spores.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.


5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Spore Trap Report: Total Counts



Ascospores	Aspergillus/Penicillium	Basidiospores	Cladosporium
Epicoccum	Ganoderma	Myxomycetes++	

* The chart is displayed using a logarithmic scale. Bar size is not directly proportional to the number of spores.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.



5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

Background Comparison Chart



* The chart is displayed using a logarithmic scale. The bar size is not directly proportional to the number of spores.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

3. Understanding the Results

EMSL Analytical, Inc. is an independent laboratory, providing unbiased and scientifically valid results. These data represent only a portion of an overall IAQ investigation. Visual information and environmental conditions measured during the site assessment (humidity, moisture readings, etc.) are crucial to any final interpretation of the results. Many factors impact the final results; therefore, result interpretation should only be conducted by qualified individuals. The American Conference of Governmental Industrial Hygienists (ACGIH) has published a good reference book covering sampling and data interpretation. It is entitled, Bioaerosols: Assessment and Control, 1999.

Fungal spores are found everywhere. Whether or not symptoms develop in people exposed to fungi depends on the nature of the fungal material (e.g., allergenic, toxic, or infectious), the exposure level, and the susceptibility of exposed persons. Susceptibility varies with the genetic predisposition (e.g., allergic reactions do not always occur in all individuals), age, pre-existing medical conditions (e.g., diabetes, cancer, or chronic lung conditions), use of immunosuppressive drugs, and concurrent exposures. These reasons make it difficult to identify dose/response relationships that are required to establish "safe" or "unsafe" levels (i.e., permissible exposure limits).

It is generally accepted in the industry that indoor fungal growth is undesirable and inappropriate, necessitating removal or other appropriate remedial actions. The New York City guidelines and EPA guidelines for mold remediation in schools and commercial buildings define the conditions warranting mold remediation. Always remember that water is the key. Preventing water damage or water condensation will prevent mold growth.

This report is not intended to provide medical advice or advice concerning the relative safety of an occupied space. Always consult an occupational or environmental health physician who has experience addressing indoor air contaminants if you have any questions.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

4. Glossary of Fungi

ASCOSPORES	
Natural Habitat	Everywhere in nature.
Suitable Substrates in the Indoor Environment	Depends on genus and species.
Water Activity	Depends on genus and species.
Mode of Dissemination	Forcible ejection or passive release and dissemination by wind or insects.
Allergic Potential	Depends on genus and species.
Potential or Opportunistic Pathogens	Depends on genus and species.
Industrial Uses	Depends on genus and species.
Potential Toxins Produced	Depends on genus and species.
Other Comments	Ascospores are the result of sexual reproduction and produced in a saclike structure called an ascus. All ascospores belong to members of the Phylum Ascomycota, which encompasses a plethora of genera worldwide.

ASPERGILLUS/PENICILLIUM	
Natural Habitat	Plant debris ·Seed ·Cereal crops
Suitable Substrates in the Indoor Environment	Grows on a wide range of substrates indoors ·Prevalent in water damaged buildings ·Foods (blue mold on cereals, fruits, vegetables, dried foods) ·House dust ·Fabrics ·Leather ·Wallpaper ·Wallpaper glue
Water Activity	Aw=0.75-0.94
Mode of Dissemination	Wind ·Insects
Allergic Potential	Type I (hay fever, asthma) ·Type III (hypersensitivity)
Potential or Opportunistic Pathogens	Possible depending on the species.
Industrial Uses	Many depending on the species
Potential Toxins Produced	Possible depending on the species.
Other Comments	Spores of Aspergillus and Penicillium (including others such as Acremonium, Talaromyces, and Paecilomyces) are small and spherical with few distinguishing characteristics. They cannot be differentiated or speciated by non-viable impaction sampling methods. Some species with very small spores may be undercounted in samples with high background debris.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

BASIDIOSPORES	
Natural Habitat	Forest floors. Lawns .Plants (saprobes or pathogens depending on genus)
Suitable Substrates in the Indoor Environment	Depends on genus. Wood products
Water Activity	Unknown.
Mode of Dissemination	Forcible ejection. Wind currents.
Allergic Potential	Type I allergies (hay fever, asthma) . Type III (hypersensitivity pneumonitis)
Potential or Opportunistic Pathogens	Depends on genus.
Industrial Uses	Edible mushrooms are used in the food industry.
Potential Toxins Produced	Amanitins. monomethyl-hydrazine. muscarine. ibotenic acid. psilocybin.
Other Comments	Basidiospores are the result of sexual reproduction and formed on a structure called the basidium. Basidiospores belong to the members of the Phylum Basidiomycota, which includes mushrooms, shelf fungi, rusts, and smuts.

CLADOSPORIUM	
Natural Habitat	Dead plant matter. Straw. Soil. Woody plants
Suitable Substrates in the Indoor Environment	Fiberglass duct liner. Paint. Textiles. Found in high concentration in water-damaged building materials.
Water Activity	Aw 0.84-0.88
Mode of Dissemination	Air
Allergic Potential	Type I (asthma and hay fever).
Potential or Opportunistic Pathogens	Edema. keratitis. onychomycosis. pulmonary infections. Sinusitis.
Industrial Uses	Produces 10 antigens.
Potential Toxins Produced	Cladospurin and Emodin.

EPICOCCUM	
Natural Habitat	A worldwide saprophytic fungi, being isolated from dead plant material and soil.
Suitable Substrates in the Indoor Environment	Paper, textiles
Water Activity	0.86-0.90
Mode of Dissemination	Wind
Allergic Potential	Hay fever, asthma
Potential or Opportunistic Pathogens	Unknown

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

GANODERMA	
Natural Habitat	Grows on conifers and hardwoods worldwide, causing white rot, root rot, and stem rot.
Suitable Substrates in the Indoor Environment	Unknown.
Water Activity	Unknown.
Mode of Dissemination	Wind.
Allergic Potential	Ganoderma species are known to cause allergies in people on a worldwide scale.
Potential or Opportunistic Pathogens	Unknown.
Industrial Uses	Biopulping of wood for the paper industry. Potential medicinal use due to: 1. Inhibition of Ras dependent cell transformation, 2. Antifibrotic activity, 3. Immunomodulating activity, 4. Free-radicle scavenging
Potential Toxins Produced	Unknown.
Other Comments	Used in traditional Chinese medicine as an herbal supplement. It is also known as a "shelf fungus" because the fruiting body forms a stalk-less shelf on the sides of trees and logs. It is sometimes called "artists conk" because when you scratch the white pores of the fruiting body, the white rubs away and exposes the brown hyphae underneath. Thus, pictures can be produced on the fruiting body.
Reference	References: Craig, R.L., Levetin, E. 2000. Multi-year study of Ganoderma aerobiology. <i>Aerobiologia</i> 16: 75-81. http://www.pfc.forestry.ca/diseases/CTD/Group/Heart/heart6_e.html

MYXOMYCETES++	
Natural Habitat	Decaying logs, Dead leaves , Dung , Lawns , Mulched flower beds, Lawns
Suitable Substrates in the Indoor Environment	Rotting lumber
Free moisture required for mold growth	Unknown
Mode of Dissemination	Insects, Water, Wind
Allergic Potential	Type I
Potential or Opportunistic Pathogens	Unknown
Industrial Uses	
Other Comments	Includes Myxomycetes, Smut, Rust, and Periconia.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

5. References and Informational Links

Books

- Bioaerosols: Assessment and Control. Janet Macher, Ed., American Conference of Governmental Industrial Hygienists, Cincinnati, OH 1999.
- Exposure Guidelines for Residential Indoor Air Quality. Environmental Health Directorate, Health Protection Branch, Health Canada, Ottawa, Ontario, 1989.
- Fungal Contamination in Public Buildings: Health Effects and Investigation Methods. Health Canada, Ottawa, Ontario, 2004.
- IICRC: S500 Standard and Reference Guide for Professional Water Damage Restoration. 3rd Edition, Institute of Inspection, Cleaning, and Restoration Certification, Vancouver, WA, 2006
- IICRC: S520 Standard and Reference Guide for Professional Mold Remediation. 1st Edition, Institute of Inspection, Cleaning, and Restoration Certification, Vancouver, WA, 2004
- Field Guide for the Determination of Biological Contaminants in Environmental Samples. 2nd Edition, American Industrial Hygiene Association, 2005.

Consumer Links

Read the full text of AIHA's "The Facts About Mold" consumer brochure.

<http://www.aiha.org/get-involved/VolunteerGroups/Documents/Biosafety/VG-FactsAbout%20MoldDecember2011.pdf>

The Occupational Safety and Health Administration (OSHA)

<http://www.osha.gov/SLTC/molds/index.html>

CDC Mold Facts

<http://www.cdc.gov/mold/faqs.htm>

CDC Stachybotrys - Questions and answers on Stachybotrys chartarum and other molds

<http://www.cdc.gov/mold/stachy.htm>

IOM, NAS: Clearing the Air: Asthma and Indoor Air Exposures

<https://www.epa.gov/indoor-air-quality-iaq/should-you-have-air-ducts-your-home-cleaned>



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108
Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

National Library of Medicine-Mold website
<http://www.nlm.nih.gov/medlineplus/molds.html>

California Department of Health Services (CADOHS)
<https://www.cdph.ca.gov/Programs/CCDPHP/DEODC/EHLB/IAQ/Pages/Mold.aspx>

Minnesota Department of Health
<http://www.health.state.mn.us/divs/eh/indoorair/mold/index.html>

New York City Department of Health and Mental Hygiene
<https://www1.nyc.gov/site/doh/health/health-topics/mold.page>

H.R.: The United States Toxic Mold Safety and Protection Act

EPA

"Should You Have the Air Ducts in Your Home Cleaned?"
<http://www.epa.gov/iaq/pubs/airduct.html>

General information about molds and actions that can be taken to clean up or prevent a mold problem.
<http://www.epa.gov/asthma/molds.html>

"A Brief Guide to Mold, Moisture, and Your Home" - Includes basic information on mold, cleanup guidelines, and moisture and mold prevention
<http://www.epa.gov/mold/moldguide.html>

"Mold Remediation in Schools and Commercial Buildings" - Information on remediation in schools and commercial property, references for potential mold and moisture remediators.
<https://www.epa.gov/mold/mold-remediation-schools-and-commercial-buildings-guide>

FEMA

"Homes That Were Flooded May Harbor Mold Problems" - Information and tips for cleaning mold.
<http://www.fema.gov/news-release/homes-were-flooded-may-harbor-mold-problems>

"Dealing With Mold & Mildew in Your Flood Damaged Home."
http://www.fema.gov/pdf/rebuild/recover/fema_mold_brochure_english.pdf



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

6. Important Terms, Conditions, and Limitations

A. Sample Retention

Samples analyzed by EMSL will be retained for 60 days after analysis date. Storage beyond this period is available for a fee with written request prior to the initial 30 day period. Samples containing hazardous/toxic substances which require special handling will be returned to the client immediately. EMSL reserves the right to charge a sample disposal fee or return samples to the client.

B. Change Orders and Cancellation

All changes in the scope of work or turnaround time requested by the client after sample acceptance must be made in writing and confirmed in writing by EMSL. If requested changes result in a change in cost the client must accept payment responsibility. In the event work is cancelled by a client, EMSL will complete work in progress and invoice for work completed to the point of cancellation notice. EMSL is not responsible for holding times that are exceeded due to such changes.

C. Warranty

EMSL warrants to its clients that all services provided hereunder shall be performed in accordance with established and recognized analytical testing procedures and with reasonable care in accordance with applicable federal, state and local laws. The foregoing express warranty is exclusive and is given in lieu of all other warranties, expressed or implied. EMSL disclaims any other warranties, express or implied, including a warranty of fitness for particular purpose and warranty of merchantability.

D. Limits of Liability

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. EMSL will not be held responsible for the improper selection of sampling devices even if we supply the device to the user. The user of the sampling device has the sole responsibility to select the proper sampler and sampling conditions to insure that a valid sample is taken for analysis. Any resampling performed will be at the sole discretion of EMSL, the cost of which shall be limited to the reasonable value of the original sample delivery group (SDG) samples. In no event shall EMSL be liable to a client or any third party, whether based upon theories

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

© 2006, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.



EMSL Analytical, Inc.

5900 4th Avenue S, Suite 100, 1st Floor Seattle, WA 98108

Phone: (206) 269-6310 Fax: (206) 900-8789 Web: <http://www.emsl.com> Email: seattlelab@emsl.com

Attn: Tim Damm
Blue Ladder Home Inspections

EMSL Order: 000000000
Customer ID: XXXX00
Collected:
Received: 11/01/2021
Analyzed: 11/02/2021

Proj: <Test Address>

of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder.

E. Indemnification

Client shall indemnify EMSL and its officers, directors and employees and hold each of them harmless for any liability, expense or cost, including reasonable attorney's fees, incurred by reason of any third party claim in connection with EMSL services, the test result data or its use by client